

## EAST Search History

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
S1	1373	(73/1.62,1.57,1.59,708).ccls.	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/11/30 09:18
S2	1062	(702/98,47,50,138).ccls.	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/11/30 09:18
S3	2389	S1 or S2	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/11/30 09:18
S5	11	(time or age) near8 (zero or zeroed or zeroing) near5 (correct or correcting or corrected or correction or compensate or compensated or compensating or compensation or calibrate or calibrated or calibrating or calibration) near13 (drift\$ or error \$) near7 (zero or zeroed or zeroing) near15 pressure	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/11/30 09:53
S6	52	(time or age) near12 (zero or zeroed or zeroing) near9 (correct or correcting or corrected or correction or compensate or compensated or compensating or compensation or calibrate or calibrated or calibrating or calibration) near15 (point or drift\$ or error\$) near17 (zero or zeroed or zeroing) near15 pressure	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/11/30 09:58
S7	5	S3 and S6	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/11/30 09:58

S8	19	(time or age) near12 (zero or zeroed or zeroing) near9 (correct or correcting or corrected or correction or compensate or compensated or compensating or compensation or calibrate or calibrated or calibrating or calibration) near15 (point or drift\$ or error\$) near17 (zero or zeroed or zeroing) near15 pressure near1 (sensor or detector or transducer)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/11/30 10:15
S9	16	S8 not S7	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/11/30 10:16
S10	4	(time or age) near2 (varying or variable or changing or varies or changes) near12 (zero or zeroed or zeroing) near9 (correct or correcting or corrected or correction or compensate or compensated or compensating or compensation or calibrate or calibrated or calibrating or calibration) near15 pressure near2 (sensor or detector or transducer)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/11/30 10:24
S11	2	S10 not (S7 or S9)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/11/30 10:43
S12	2	"5146941".pn.	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/11/30 13:48

5/2/2008 8:58:11 AM

C:\Documents and Settings\raevis\My Documents\EAST\Workspaces\10561602.wsp